Repair Price List

1) Movement related repair price list

Qua	artz · Solar	CS-36	CC/AC-39	SQ-32	CT-27	CD-40	CS-32	CJ-32	TS-36/TS1-36	STS-38/STS-32	TSC-39	CMP-38	CMP-34	Repair Content
battery	y replacement	¥2,200	¥2,200	¥2,200	¥2,200	¥2,200	movement exchange only	movement exchange only	movement exchange only	movement exchange only	movement exchange only	¥2,200	¥2,200	battery replacement + water resistent test replacement of a watch back gasket + demagnetization service
movem	nent exchange	¥5,500	¥7,150	¥5,500	¥5,500	¥5,500	¥7,700	¥7,700	¥7,700	¥8,250	¥8,800	¥7,150	¥5,500	movement exchange + water resistent test replacement of a watch back gasket + running test + demagnetization service

Automatic	CAP-38	AT-38	AT-40S	ATC-40	Repair Content			
movement exchange	¥11,550	¥17,050	¥17,050	¥39,050	battery replacement + water resistent test replacement of a watch back gasket + demagnetization service			

2) Exterior Repair Price List (technical fee + exterior parts fee) For exterior repairs, the price includes both technical fees and exterior parts' fees.

technical fee

Watch Model No.	CS-36	CC/AC-39	SQ-32	CT-27	CD-40	CS-32	CJ-32	TS-36/TS1-36	STS-38/STS-32	TSC-39	CMP-38	CMP-34	CAP-38	AT-38	AT-40S/AT1-40S	ATC-40
technical fee	¥3,300	¥3,300	¥3,300	¥3,300	¥3,300	¥3,300	¥3,300	¥3,300	¥3,300	¥3,300	¥3,300	¥3,300	¥6,050	¥9,350	¥9,350	¥13,750

+			+													
exterior parts' fee																
Watch Model No.	CS-36	CC/AC-39	SQ-32	CT-27	CD-40	CS-32	CJ-32	TS-36/TS1-36	STS-38/STS-32	TSC-39	CMP-38	CMP-34	CAP-38	AT-38	AT-40S	ATC-40
sapphire glass	¥2,750	¥3,300	same price as case	same price as case	¥3,300	¥3,300	¥3,300	¥3,300	¥3,300	¥3,300	¥3,300	¥3,300	¥4,400	same price as case	same price as case	same price as case
dial	¥2,200	¥2,750	¥2,200	¥2,200	¥2,750	¥2,750	¥3,850	¥2,750	¥2,750	¥3,300	¥2,200	¥2,200	¥3,300	¥4,400	¥7,700	¥7,700
case(SV)	¥3,850	¥4,400	¥6,600	¥6,600	¥4,400	¥5,500	¥5,500	¥5,500	¥6,600	¥8,800	¥5,500	¥5,500	¥5,500	¥16,500 including glass and back case	¥24,200 including glass and back case	¥24,200 including glass and back case
case(IP coating)	¥4,950	¥5,500	¥7,700	¥7,700	¥5,500	¥6,600	¥6,600	¥6,600	¥7,700	¥9,900	¥6,600	¥6,600	¥7,700	¥22,000 including glass and back case	-	-
back case	¥1,100	¥1,100	¥1,100	¥1,100	¥1,100	¥1,100	¥1,100	¥1,650	¥1,100	¥2,750	¥1,100	¥1,100	¥1,100	same price as case	same price as case	same price as case
crown	¥1,100	¥1,100	¥1,100	¥1,100	¥1,100	¥1,100	¥1,100	¥1,650	¥1,100	¥1,650	¥1,100	¥1,100	¥1,100	¥2,200	Case replacement only to ensure water resistent function	¥2,200
hands	¥1,100	¥1,650	¥1,100	¥1,100	¥1,100	¥1,100	¥1,100	¥1,100	¥1,100	¥1,650	¥1,650	¥1,100	¥1,650	¥1,650	¥2,200	¥2,200

3) Machanical watch overhaul price list every 3-4 years is recommended.

Watch Model No.	CAP-38	AT-38	AT-40S	ATC-40	Repair Content
maintainance movement exchange / overhaul	-	¥17,050	¥17,050	¥39,050	including water resistent test+replacement of a watch back gasket+running test,
%optional case polishing	-	¥13,200	-	¥16,500	Watch model AT-40S is not available for polishing service because of engraving on tachymeter

NIT he above polishing service is an option for OH / Movt replacement, it is not available as a stand-alone service at this time.